



CONSTRUCTION EQUIPMENT

VOLVO A45G 342542 - FRONT AXLE



Sample No: VCP0007612
Oil Type: GEAR OIL SAE 80W140
Job No:



ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: TECHNICIAN ACCOUNT
 catherine.anastasio@wearcheck.com
 T:
 F: (904)737-1260



SAMPLE INFORMATION

Sample Number	VCP0007612	---	---	---
Sample Date	28 Jun 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	6304	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 293	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 8	---	---	---



WEAR METALS

Iron	ppm	█ 76	---	---	---
Copper	ppm	█ 2	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 49	---	---	---
Magnesium	ppm	█ 19	---	---	---
Zinc	ppm	█ 41	---	---	---
Phosphorus	ppm	█ 1033	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 201	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0092
Unique No: 10547433
Signed: Doug Bogart
Report Date: 07 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS

