



# CONSTRUCTION EQUIPMENT

## VOLVO L220H 2890 - FRONT AXLE



**Sample No:** VCP410200  
**Oil Type:** TDH FLUID SAE 75W80  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP410200	---	---	---
Sample Date	05 Jul 2023	---	---	---
Machine Hours	10844	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ROMCO INC**  
 1350 NE LOOP 820  
 FORT WORTH, TX  
 US 76106  
 Contact: CHRIS BITNER  
 CBitner@romco.com  
 T:  
 F: (817)626-8983

### OIL CONDITION

Visc @ 40°C	cSt	█ 41.7	---	---	---
-------------	-----	--------	-----	-----	-----

### CONTAMINATION

Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 8	---	---	---
Potassium	ppm	█ 2	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

### WEAR METALS

Iron	ppm	█ 67	---	---	---
Copper	ppm	█ 3	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---

### ADDITIVES

Calcium	ppm	█ 3373	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1469	---	---	---
Phosphorus	ppm	█ 1177	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 117	---	---	---

**Depot:** VOLVO0081  
**Unique No:** 10547478  
**Signed:** Don Baldrige  
**Report Date:** 08 Jul 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

