

## CONSTRUCTION EQUIPMENT CHARAH VOLVO A30G 752545 - DIESEL ENGINE



Sample No: VCP404933
Oil Type: NOT GIVEN
Job No: CHARAH

SAMPLE II	NFORMATION		 	
Sample Number		VCP404933	 	
Sample Date		06 Jul 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	<b>15.0</b>	 	
Base Number (BN)	mg KOH/g	■8.5	 	
Oxidation (PA)	%	13	 	
CONTAMIN	IATION			
CONTAMIN				<u> </u>
Soot %	%	■0.1	 	
Nitration (PA)	%	35	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>■</b> 2	 	
Potassium	ppm	<b>0</b>	 	
VOLVO				
<b>WEAR ME</b>	TALS			
ron	ppm	<b>^</b> 269	 	
Copper	ppm	<b>7</b>	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	■5	 	
Molybdenum	ppm	<b>■4</b>	 	
Nickel	ppm	<b>2</b>	 	
Titanium	ppm	0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	5	 	
Vanadium	ppm	0	 	



SCOTT EQUIPMENT COMPANY LLC - Springdale
4831 NORTH THOMPSON
SPRINGDALE, AR
US 72764
Contact: DERRICK BRINK
dbrink@scottcompanies.com
T: (479)751-4242
F:

## Diagnosis

We suspect abnormal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor. Cylinder, crank, or cam shaft wear is indicated. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is suitable for further service.

Depot:SCOSPRUnique No:10547693Signed:Doug BogartReport Date:09 Jul 2023

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

**2404** 

**14** 

**990** 

**1130** 

**0** 

**62** 



## **CONSTRUCTION EQUIPMENT**





