

CONSTRUCTION EQUIPMENT

X58196 VOLVO EC350EL 314462 - REAR RIGHT FINAL DRIVE

Sample No: VCP425335
Oil Type: NOT GIVEN
Job No: X58196

VOLVO				
SAMPLE	INFORMATION			
Sample Number		VCP425335	 	
Sample Date		03 Jul 2023	 	
Machine Hours		1169	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		SEVERE	 	
OIL COND	ITION			
Visc @ 40°C	cSt	172	 	
		_		
VOLVO	MATION			
CONTAMI	NATION	-		
Silicon	ppm	479	 	
Sodium	ppm	12	 	
Potassium	ppm	■31	 	
VOLVO				
WEAR MI	ETALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	■ 2	 	
Lead	ppm	■0	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	2 6	 	
Molybdenum	ppm	2	 	
Nickel	ppm	1	 	
Titanium	ppm	6	 	
Silver	ppm	0	 	
Manganese	ppm	13	 	
Vanadium	ppm	<1	 	
VOLVO			 	
ADDITIVI	2			
Calcium	ppm	30	 	
Magnesium	ppm	19	 	
Zinc		_		
	ppm	7	 	
Phosphorus	ppm	7 328	 	



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997

SAINT ROSE, LA US 70087

Contact: DENISE CORVERS dcorvers@scottcompanies.com

T: (504)461-0961 F: (504)461-0970

Diagnosis

We advise that you check all areas where dirt can enter the system. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10548342Signed:Don BaldridgeReport Date:10 Jul 2023



CONSTRUCTION EQUIPMENT





