



CONSTRUCTION EQUIPMENT

568852 VOLVO A30 753369 - TRANSMISSION



Sample No: VCP411687
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 568852



SAMPLE INFORMATION

Sample Number	VCP411687	---	---	---
Sample Date	03 Jul 2023	---	---	---
Machine Hours	255	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

BLUE GOOSE GROWERS
 16059 W ORANGE AVE
 FT PIERCE, FL
 US 34945
 Contact: SERVICE MANAGER



OIL CONDITION

Visc @ 40°C	cSt	█ 28.7	---	---	---
-------------	-----	--------	-----	-----	-----

T: (772)461-3020
 F:



CONTAMINATION

Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis
 Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 14	---	---	---
Copper	ppm	█ 11	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 8	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	█ 0	---	---	---



ADDITIVES

Calcium	ppm	█ 71	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 187	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 91	---	---	---

Depot: BLUFOR
Unique No: 10548364
Signed: Wes Davis
Report Date: 10 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS


Iron (ppm)



Lead (ppm)




Aluminum (ppm)




Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Additives

