



CONSTRUCTION EQUIPMENT

VOLVO A45G 342545 - COOLANT



Sample No: VCP0007596

Oil Type: NOT GIVEN

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007596	---	---	---
Sample Date	06 Jul 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.60	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 46.3	---	---	---
Freezing Point	°C	■ -26	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---



QGS - QUALITY GRASSES SERV/TCF LEASING
 17502 CR 672
 LITHIA, FL
 US 33547
 Contact: GARY ROGERS
 grogers@qgsdevelopment.com
 T: (813)323-4119
 F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: QUALITFL
Unique No: 10549999
Signed: Jonathan Hester
Report Date: 12 Jul 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

