



# CONSTRUCTION EQUIPMENT

## VOLVO A45G 342540 - COOLANT



**Sample No:** VCP0007587

**Oil Type:** NOT GIVEN

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP0007587	---	---	---
Sample Date	06 Jul 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

**QGS - QUALITY GRASSES SERV/TCF LEASING**  
 17502 CR 672  
 LITHIA, FL  
 US 33547  
 Contact: GARY ROGERS  
 grogers@qgsdevelopment.com  
 T: (813)323-4119  
 F:



### COOLANT CONDITION

pH	Scale 0-14	■ 7.91	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.9	---	---	---
Freezing Point	°C	■ -35	---	---	---

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



### CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** QUALITFL  
**Unique No:** 10550000  
**Signed:** Jonathan Hester  
**Report Date:** 12 Jul 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

