



CONSTRUCTION EQUIPMENT

VOLVO A45G 342538 - COOLANT



Sample No: VCP0007976

Oil Type: NOT GIVEN

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007976	---	---	---
Sample Date	06 Jul 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

QGS - QUALITY GRASSES SERV/TCF LEASING
 17502 CR 672
 LITHIA, FL
 US 33547
 Contact: GARY ROGERS
 grogers@qgsdevelopment.com
 T: (813)323-4119
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 8.18	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 46.5	---	---	---
Freezing Point	°C	■ -26	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: QUALITFL
Unique No: 10550001
Signed: Jonathan Hester
Report Date: 12 Jul 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

