



CONSTRUCTION EQUIPMENT

566310 RE BECKNER VOLVO A25G 752540 - FRONT AXLE



Sample No: VCP411591
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: 566310 RE BECKNER



SAMPLE INFORMATION

Sample Number	VCP411591	---	---	---
Sample Date	15 Jun 2023	---	---	---
Machine Hours	779	---	---	---
Oil Hours	779	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: JOHN FARDELLA
 JFARDELLA@ALTAEQUIPFL.COM
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	▲ 90.1	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 5	---	---	---
Sodium	ppm	■ 1	---	---	---
Potassium	ppm	■ 4	---	---	---



WEAR METALS

Iron	ppm	■ 186	---	---	---
Copper	ppm	■ 23	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 5	---	---	---
Molybdenum	ppm	■ 8	---	---	---
Nickel	ppm	■ 3	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	2	---	---	---
Manganese	ppm	■ 11	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	▲ 877	---	---	---
Magnesium	ppm	■ 2	---	---	---
Zinc	ppm	▲ 391	---	---	---
Phosphorus	ppm	■ 1350	---	---	---
Barium	ppm	■ <1	---	---	---
Boron	ppm	■ 238	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type.

Depot: VOLVO0093
Unique No: 10551171
Signed: Sean Felton
Report Date: 13 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS

