

# CONSTRUCTION EQUIPMENT 568198 VOLVO A30G 752866 - FRONT AXLE



Sample No: VCP422143

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** 568198

SAMPLI	E INFORMATIO	1		
Sample Number	<u> </u>	VCP422143	VCP402757	 
Sample Date		05 Jul 2023	13 Feb 2023	 
Machine Hours		1096	526	 
Oil Hours		500	526	 
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 
OIL CON	INITIAN			
Visc @ 40°C	cSt	<b>199</b>	■89.7	 
VOLVO				
CONTAR	MINATION			
Silicon	ppm	<b>■</b> 3	<b>5</b>	 
Sodium	ppm	<b>III&lt;1</b>	1	 
Potassium	ppm	<b>1</b>	<b>1</b> 4	 
	le le			
WEAR N	METALS			
Iron	ppm	□106	□252	 
Copper	ppm	<b>7</b>	<b>1</b> 5	 
Lead	ppm	O	<b>0</b>	 
Tin	ppm	<b>-&lt;1</b>	<b>-</b> <1	 
Aluminum	ppm	<u> </u>	<u> </u>	 
Chromium	ppm	<b>2</b>	<b>6</b>	 
Molybdenum	ppm	<b>5</b>	■11	 
Nickel	ppm	<b>1</b>	<b>4</b>	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	<b>4</b>	□9	 
Vanadium	ppm	0	0	 
ADDITIV	VES			
Calcium	ppm	■306	□906	 
Magnesium	ppm	<b>1</b> 5	<b>4</b>	 
Zinc	ppm	■138	■381	 
Phosphorus	ppm	■1082	1271	 
Barium	ppm	■0	<b>■</b> 3	 
Boron	ppm	<b>172</b>	<b>254</b>	 



### RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10551172Signed:Sean FeltonReport Date:13 Jul 2023



## **CONSTRUCTION EQUIPMENT**





