



# CONSTRUCTION EQUIPMENT

568198 VOLVO A30G 752866 - REAR AXLE



**Sample No:** VCP422140  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 568198



## SAMPLE INFORMATION

Sample Number	VCP422140	VCP402760	---	---
Sample Date	05 Jul 2023	13 Feb 2023	---	---
Machine Hours	1096	526	---	---
Oil Hours	500	526	---	---
Oil Changed	Not Chngd	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

### RIPA AND ASSOCIATES

10149 FISHER AVENUE  
TAMPA, FL  
US 33619  
Contact: ROBERT TURNER  
rturner@ripatampa.com  
T:  
F:



## OIL CONDITION

Visc @ 40°C	cSt	█ 206	█ 89.3	---	---
-------------	-----	-------	--------	-----	-----



## CONTAMINATION

Silicon	ppm	█ 2	█ 8	---	---
Sodium	ppm	█ <1	█ 2	---	---
Potassium	ppm	█ 2	█ 5	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 104	█ 318	---	---
Copper	ppm	█ 6	█ 13	---	---
Lead	ppm	█ 0	█ 0	---	---
Tin	ppm	█ 0	█ <1	---	---
Aluminum	ppm	█ 1	█ <1	---	---
Chromium	ppm	█ 2	█ 6	---	---
Molybdenum	ppm	█ 4	█ 8	---	---
Nickel	ppm	█ <1	█ 3	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	█ 3	█ 10	---	---
Vanadium	ppm	0	0	---	---



## ADDITIVES

Calcium	ppm	█ 277	█ 892	---	---
Magnesium	ppm	█ 16	█ 2	---	---
Zinc	ppm	█ 126	█ 368	---	---
Phosphorus	ppm	█ 1066	1259	---	---
Barium	ppm	█ 0	█ 3	---	---
Boron	ppm	█ 174	█ 255	---	---

**Depot:** RIPTAM  
**Unique No:** 10551179  
**Signed:** Sean Felton  
**Report Date:** 13 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

