CONSTRUCTION EQUIPMENT RENTAL VOLVO ECR145EL 315482 - HYDRAULIC SYSTEM

Sample No:	VCP422943
Oil Type:	VOLVO SUPER HYDRAULIC OIL 46
Job No:	RENTAL

SAMPLE INFORMATION

VOLVO

Sample Number	-	VCP422943	VCP367285	
Sample Date		03 Jul 2023	03 Oct 2022	
Machine Hours		2063	1443	
Oil Hours		500	1443	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CONDI	TION			
Visc @ 40°C	cSt	42.3	42.9	
Acid Number (AN)	mg KOH/g	0.51	0.43	
VOLVO				

	MINATION				
Particles >4µm	-	31802	11600	 	
Particles >6µm		9819	2884	 	
Particles >14µm		840	207	 	
ISO 4406:1999 (c))	22/20/17	21/19/15	 	
Silicon	ppm	6	7	 	
Sodium	ppm	■ <1	0	 	
Potassium	ppm	0	<1	 	

OLVO	
	WEAD MET

WEAK N	AFIAL2			
Iron	ppm	1	2	
Copper	ppm	24	21	
Lead	ppm	0	< 1	
Tin	ppm	0	<1	
Aluminum	ppm	■ <1	<1	
Chromium	ppm	0	<1	
Molybdenum	ppm	0	0	
Nickel	ppm	0	0	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	0	 <1	
Vanadium	ppm	<1	0	

ADDITI	IVES			
Calcium	ppm	42	53	
Magnesium	ppm		<1	
Zinc	ppm	461	506	
Phosphorus	ppm	383	371	
Barium	ppm	0	2	
Boron	ppm	0	0	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:	VOLVO0093
Unique No:	10551881
Signed:	Wes Davis
Report Date:	13 Jul 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

