
CONSTRUCTION EQUIPMENT X58223 VOLVO ECR235EL 315285 - HYDRAULIC SYSTEM

Sample No:	VCP425334
Oil Type:	AW HYDRAULIC OIL ISO 46
Job No:	X58223

### SAMPLE INFORMATION

VOLVO

Sample Number		VCP425334				
Sample Date		05 Jul 2023				
Machine Hours		992				
Oil Hours		0				
Oil Changed		Not Changd				
Sample Status		NORMAL				
OIL CONDITION						
Visc @ 40°C	cSt	<b>42.3</b>				
Acid Number (AN)	mg KOH/g	0.51				
CONTAMIN	IATION					
Particles >4µm	-	10925				
Particles >6µm		2399				
Particles > 14um		<b>160</b>				



## WEAR METALS

Iron	ppm	2	 	
Copper	ppm	20	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	<1	 	

	IVES			
Calcium	ppm	68	 	
Magnesium	ppm		 	
Zinc	ppm	509	 	
Phosphorus	ppm	397	 	
Barium	ppm	0	 	
Boron	ppm	0	 	



#### SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997

SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961 F: (504)461-0970

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10551893Signed:Angela BorellaReport Date:13 Jul 2023

# **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

