

CONSTRUCTION EQUIPMENT
BECKNER CONST VOLVO EC480 315121 - LEFT SWING DRIVE

Sample No: VCP422940 Oil Type: **VOLVO** 

Job No: **BECKNER CONST** 

CVMDIE	INFORMATIO	V		
	INFURMATIU	<u> </u>		
Sample Number		VCP422940	 	
Sample Date		30 Jun 2023	 	
Machine Hours		511	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	<b>160</b>		
	CSL	<b>100</b>	 	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	<b>11</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>0</b>	 	
T ottassiaiii	PPIII			
VOLVO				
WEAR M	ETALS			
Iron	ppm	■86	 	
Copper	ppm	<b>■28</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>■</b> 2	 	
Molybdenum	ppm	4	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
ADDITIV	TC			
	_			
Calcium	ppm	69	 	
Magnesium	ppm	4	 	
Zinc	ppm	43	 	
Phosphorus	ppm	341	 	
Barium	ppm	0	 	
Boron	ppm	<1	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093 **Unique No:** 10552321 Signed: Don Baldridge Report Date: 13 Jul 2023



## **CONSTRUCTION EQUIPMENT**





