



# CONSTRUCTION EQUIPMENT

TURNER PAVING VOLVO A25G 752444 - TRANSMISSION (AUTO)



**Sample No:** VCP418282  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** TURNER PAVING



## SAMPLE INFORMATION

Sample Number	VCP418282	---	---	---
Sample Date	11 Jul 2023	---	---	---
Machine Hours	1688	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
9601 BOGGY CREEK RD  
ORLANDO, FL  
US 32824  
Contact: Robert LaPlante  
robert.laplante@altg.com  
T: (407)508-9736  
F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	█ 28.9	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ <1	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 27	---	---	---
Copper	ppm	█ 25	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 4	---	---	---
Aluminum	ppm	█ 22	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 68	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 195	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 81	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 10552380  
**Signed:** Wes Davis  
**Report Date:** 13 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS


### Iron (ppm)




### Lead (ppm)



### Aluminum (ppm)




### Chromium (ppm)



### Copper (ppm)



### Silicon (ppm)



### Viscosity @ 40°C



### Additives

