



CONSTRUCTION EQUIPMENT

VOLVO L70H L70H 623647 - COOLANT



Sample No: VCP0007991
Oil Type: HYBRID (HOAT) COOLANT
Job No:



SAMPLE INFORMATION

Sample Number	VCP0007991	---	---	---
Sample Date	10 Jul 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: TECHNICIAN ACCOUNT
 catherine.anastasio@wearcheck.com
 T:
 F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	■ 7.54	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 48.7	---	---	---
Freezing Point	°C	■ -31	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO0092
Unique No: 10552460
Signed: Doug Bogart
Report Date: 16 Jul 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

