

CONSTRUCTION EQUIPMENT

ASCENDUM MACHINERY 500HR CSA/TRIANGLE GRADING 19006



Sample No: VCP407549

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 19006

ZAMPI F	INFORMATION				
	INI ONI-IATION		VCD202C40	VCD222720	
Sample Number		VCP407549	VCP382649	VCP322739	
Sample Date		03 Jul 2023	20 Feb 2023	06 Jun 2021	
Machine Hours		6473	6088	4108	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Changed	Changed	
Sample Status		SEVERE	SEVERE	ABNORMAL	
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	404	▲ 790	■325	
VOLVO	IINATION				
	IINATION				
Water	%	<u> </u>	△ 0.468		
Silicon	ppm	1174	1848	<u>448</u>	
Sodium	ppm	■ 59	■110	■20	
Potassium	ppm	68	123	2 2	
WEAR M	IFTALS				
Iron	ppm	2276	3709	<u> </u>	
Copper	ppm	4	8	1 2	
Lead	ppm	- <1	□ <1	- <1	
Tin	ppm	- <1	<1	- <1	
Aluminum	ppm	<u>▲</u> 325	<u>▲</u> 506	▲ 139	
Chromium	ppm	<u> </u>	38	<u>▲</u> 15	
Molybdenum	ppm	2	1 4	1	
Nickel	ppm	<u> </u>	7	1	
Titanium	ppm	18	m33	9	
Silver	ppm	0	0	0	
Manganese	ppm	■ 15	2 3	□ 11	
Vanadium	ppm	<1	1	<1	
	PPIII			. ,	
VOLVO					
ADDITIV	FZ				
Calcium	ppm	■ 59	□ 96	□30	
Magnesium	ppm	42	6 5	□14	
Zinc	ppm	16	1 5	1 0	
Phosphorus	ppm	■998	■851	□ 642	
Barium	ppm	2	■ 3	0	
Boron	ppm	140	146	■48	



TRIANGLE GRADING AND PAVING INC

1521 Huffman Mill Rd BURLINGTON, NC US 27216 Contact: KAREN HILLIARD khilliard@trianglegradingpaving.com T: (336)584-1745

F: (336)584-0145

Diagnosis

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. There is a light concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot: TRIBUR
Unique No: 10552879
Signed: Don Baldridge
Report Date: 14 Jul 2023



CONSTRUCTION EQUIPMENT





