



CONSTRUCTION EQUIPMENT

302549 VOLVO EC220 314775 - COOLANT



Sample No: VCP417973
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 302549



SAMPLE INFORMATION

Sample Number	VCP417973	---	---	---
Sample Date	13 Jul 2023	---	---	---
Machine Hours	1000	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 8.10	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 46.5	---	---	---
Freezing Point	°C	■ -26	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

CASCADES RECOVERY US

1845 EMERSON ST
 ROCHESTER, NY
 US 146063123
 Contact: SERVICE MANAGER

T: (585)527-8110
 F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: METROC
Unique No: 10560489
Signed: Jonathan Hester
Report Date: 18 Jul 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

