

# **CONSTRUCTION EQUIPMENT**

361 CATERPILLAR DLSO 1977 - FRONT LEFT FINAL DRIVE

Sample No: VCP396793

**Oil Type:** DRYDENE LIMITED SLIP GEAR 80W90

**Job No:** 361

VOLVO					
SAMPLE	INFORMATION				
Sample Number	-	VCP396793			
Sample Date		26 Jun 2023			
Machine Hours		6752			
Oil Hours		1000			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>140</b>			
VOLVO					
CONTAN	MINATION				
Silicon	ppm	<b>■</b> 95			
Sodium	ppm	<b>■</b> 3			
Potassium	ppm	<b>11</b>			
WEAR N	AETALS				
_					
Iron	ppm	<b>450</b>			
Copper	ppm	<b>□</b> <1			
Lead	ppm	<b>0</b>			
Tin	ppm	<b>0</b>			
Aluminum	ppm	<b>25</b>			
Chromium	ppm	<b>2</b>			
Molybdenum	ppm	<b>1</b>			
Nickel	ppm	<b>■</b> <1			
Titanium	ppm	<b>3</b>			
Silver	ppm	<b>□</b> 0 4			
Manganese Vanadium	ppm	4 <1			
variaululli	ppm	<b>N</b> 1			
VOLVO					
ADDITIN	/ES				
Calcium	ppm	<b>122</b>			
Magnesium	ppm	<b>9</b>			
Zinc	ppm	■38			
Phosphorus	ppm	<b>635</b>			
Barium	ppm	<b>■</b> 0			
Boron	ppm	<b>53</b>			



### TOTAL DEVELOPMENT SOLUTIONS LLC

7805 PROGRESS CT
GAINESVILLE, VA
US 20155
Contact: JOE SEALE
jseale@totaldevelopmentsolutions.com
T: (703)222-0497
F: (703)753-4586

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:TOTGAIUnique No:10560821Signed:Don BaldridgeReport Date:18 Jul 2023

Contact/Location: JOE SEALE - TOTGAI



# **CONSTRUCTION EQUIPMENT**





