



CONSTRUCTION EQUIPMENT

SWA305799 ESPERAZA TORO TX1000 412678973 - DIESEL FUEL



Sample No: VCP420191
Oil Type: NOT GIVEN
Job No: SWA305799 ESPERAZA



SAMPLE INFORMATION

Sample Number	VCP420191	VCP419504	---	---
Sample Date	11 Jul 2023	10 Jul 2023	---	---
Machine Hours	186	186	---	---
Sample Status	NORMAL	NORMAL	---	---

ALTA EQUIPMENT CO - ORLAND PARK
5000 INDUSTRIAL HWY
GARY, IN
US 46406
Contact: DAVE ENG
DAVE.ENG@ALTG.COM
T: (312)350-2560
F:



FUEL CONDITION

Sulfur	ppm	0	0	---	---
Visc @ 40°C	cSt	2.95	2.95	---	---



CONTAMINATION

Water	%	0.011	0.012	---	---
Lead	ppm	0	0	---	---
Nickel	ppm	<1	<1	---	---
Aluminum	ppm	0	0	---	---
Vanadium	ppm	0	0	---	---
Silicon	ppm	<1	<1	---	---

Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time. All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot: VOLVO8885
Unique No: 10560866
Signed: Jonathan Hester
Report Date: 18 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS

Pensky-Martens Flash Point (°C)

