



CONSTRUCTION EQUIPMENT

SWA286531-10 VOLVO L90H 623596 - COOLANT



Sample No: VCP407428
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA286531-10



SAMPLE INFORMATION

Sample Number	VCP407428	VCP376192	VCP328191	VCP316705
Sample Date	28 Jun 2023	22 Aug 2022	16 Dec 2021	28 Jul 2021
Machine Hours	11338	10360	9295	8765
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



COOLANT CONDITION

pH	Scale 0-14	7.25	7.22	7.25	7.23
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	0	0	0
Percentage Glycol	%	52.2	52.4	52	52
Freezing Point	°C	-40	-40	-43	-43



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow



IAA - INSURANCE AUTO AUCTIONS - ROCK TAVERN
 39 STONE CASTLE RD
 ROCK TAVERN, NY
 US 12575
 Contact: SERVICE MANAGER

T:
F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: INSROC
Unique No: 10561730
Signed: Jonathan Hester
Report Date: 20 Jul 2023




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

