



# CONSTRUCTION EQUIPMENT

## 10736 VOLVO A40G 353156 - FRONT AXLE



**Sample No:** VCP416446  
**Oil Type:** VOLVO SUPER GEAR OIL 75W-80-GO102  
**Job No:** 10736



**HOFFMAN EQUIPMENT - LIONVILLE**  
 120 GORDON DRIVE  
 LIONVILLE, PA  
 US 19341  
 Contact: JIM FEHR  
 jim.fehr@hoffmanequip.com  
 T: (610)363-9200  
 F: (610)594-0829



### SAMPLE INFORMATION

Sample Number	VCP416446	---	---	---
Sample Date	12 Jul 2023	---	---	---
Machine Hours	803	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



### OIL CONDITION

Visc @ 40°C	cSt	█ 57.8	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 1	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 3	---	---	---



### WEAR METALS

Iron	ppm	█ 60	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	█ 0	---	---	---



### ADDITIVES

Calcium	ppm	█ 71	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 32	---	---	---
Phosphorus	ppm	█ 1634	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 182	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO8879  
**Unique No:** 10562993  
**Signed:** Don Baldrige  
**Report Date:** 20 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

