

CONSTRUCTION EQUIPMENT A10740 VOLVO A40G 352138 - REAR AXLE



Sample No: VCP411933

Oil Type: MOBIL MOBILUBE HD 80W90

Job No: A10740

CAMDIE	INFORMATION			
	INFURMATION	<u> </u>		
Sample Number		VCP411933	VCP310240	
Sample Date		13 Jul 2023	30 Jul 2021	
Machine Hours		7031	2075	
Oil Hours		0	1000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CONE	NITION			
Visc @ 40°C		=126	T 152	
	cSt	126	■152	
VOLVO				
CONTAM	INATION			
Silicon	ppm	8	<u></u> 2	
Sodium	ppm	0	4	
Potassium	ppm	■<1	0	
	ρρ			
VOLVO				
WEAR M	FIALS			
Iron	ppm	135	□79	
Copper	ppm	■<1	- <1	
Lead	ppm	0	< 1	
Tin	ppm	■ 0	- <1	
Aluminum	ppm	■<1	< 1	
Chromium	ppm	2	1	
Molybdenum	ppm	□ <1	< 1	
Nickel	ppm	■ 0	0	
Titanium	ppm	0	<1	
Silver	ppm	0	<1	
Manganese	ppm	2	2	
Vanadium	ppm	0	0	
ADDITIV	FC			
	_			
Calcium	ppm	■32	6 5	
Magnesium	ppm		4	
Zinc	ppm	1 4	2 4	
Phosphorus	ppm	492	■926	
Barium	ppm	0	0	
Boron	ppm	■31	275	



RUGGIERO EXCAVATING LLC

930 EAST MARKET STREET BETHLEHEM, PA US 18017

Contact: SERVICE MANAGER

T: (610)691-5993 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RUGBETUnique No:10563010Signed:Don BaldridgeReport Date:20 Jul 2023



CONSTRUCTION EQUIPMENT





