



# CONSTRUCTION EQUIPMENT

10736 VOLVO A40G 353156 - TRANSMISSION (AUTO)



**Sample No:** VCP416452  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 10736



## SAMPLE INFORMATION

Sample Number	VCP416452	---	---	---
Sample Date	12 Jul 2023	---	---	---
Machine Hours	803	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**HOFFMAN EQUIPMENT - LIONVILLE**  
 120 GORDON DRIVE  
 LIONVILLE, PA  
 US 19341  
 Contact: JIM FEHR  
 jim.fehr@hoffmanequip.com  
 T: (610)363-9200  
 F: (610)594-0829



## OIL CONDITION

Visc @ 40°C	cSt	█ 34.9	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 2	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 0	---	---	---
Copper	ppm	█ < 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ < 1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ < 1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 97	---	---	---
Magnesium	ppm	█ 5	---	---	---
Zinc	ppm	█ 5	---	---	---
Phosphorus	ppm	█ 242	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 90	---	---	---

**Depot:** VOLVO8879  
**Unique No:** 10563051  
**Signed:** Wes Davis  
**Report Date:** 19 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

