

Sample No: VCP416311

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No: SWA310208 WOOD MEAD

CVMDLLI	NFORMATION				
	II OMPATION				_
Sample Number		VCP416311	VCP394014		
Sample Date		13 Jul 2023	31 Jan 2023		
Machine Hours		8238	8449		
Sample Status		NORMAL	NORMAL		
COOLANT CONDITION					
рН	Scale 0-14	■8.08	<b>7.68</b>		
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	<b>0</b>	<b>448</b>		
Percentage Glycol	%	■39.2	<b>48.2</b>		
Freezing Point	°C	<b>-11</b>	<b>□</b> -31		
CONTAMINATION					
Coolant Appearance		normal	normal		
Coolant Color		Pink	Yllow		



ALTA EQUIPMENT COMPANY - METRO WEST 56195 PONTIAC TRAIL NEW HUDSON, MI US 48165 Contact: JEFF YAEK jeff.yaek@altaequipment.com T: (248)770-6328

F: x:

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO2990Unique No:10563122Signed:Doug BogartReport Date:24 Jul 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

