

CONSTRUCTION EQUIPMENT

286664 PASCO EXC VOLVO L150H 7073 - HYDRAULIC SYSTEM

Sample No: VCP418269

Oil Type: **VOLVO SUPER HYDRAULIC OIL 46**

Job No: 286664 PASCO EXC

SAMPLE II	NFORMATION			
Sample Number		VCP418269	 	
Sample Date		21 Jun 2023	 	
Machine Hours		2043	 	
Oil Hours		2043	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	42.1	 	
Acid Number (AN)	mg KOH/g	■ 0.35	 	
CONTAMIN	NATION			
Particles >4µm	-	□3688	 	
Particles >6µm		■523	 	
Particles >14µm		■24	 	
ISO 4406:1999 (c)		19/16/12	 	
Silicon	ppm	■3	 	
Sodium	ppm	2	 	
Potassium	ppm	■ 0	 	
WEAR ME	TALS			
Iron	ppm		 	
Copper	ppm	■3	 	
_ead	ppm	□0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■ <1	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	□ <1	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	<1	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA JFARDELLA@ALTAEQUIPFL.COM T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 10565655 Signed: Wes Davis Report Date: 24 Jul 2023

43

1

0

0

383 ■307

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus



CONSTRUCTION EQUIPMENT





GRAPH

