

# CONSTRUCTION EQUIPMENT 579653 VOLVO A40G 353131 - REAR AXLE



Sample No: VCP422686

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** 579653

SAMPLE	INFORMATION				
Sample Number	_	VCP422686			
Sample Date		13 Jul 2023			
Machine Hours		2234			
Oil Hours		1500			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	□309			
V13C @ 40 C	CSt				
VOLVO					
CONTAM	INATION				
Silicon	ppm	■37			
Sodium	ppm	<b>□</b> 0			
Potassium	ppm	<b>1</b>			
WEAR M	ETALS				
Iron	ppm	<b>170</b>			
Copper	ppm	<b>■</b> 4			
Lead	ppm	<b>■</b> <1			
Tin	ppm	<b>■</b> 0			
Aluminum	ppm	<b></b>			
Chromium	ppm	<b>2</b>			
Molybdenum	ppm	<b>2</b>			
Nickel	ppm	<b>1</b>			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	■3			
Vanadium	ppm	0			
VOLVO					
ADDITIV	ES				
Calcium	ppm	<b>111</b>			
Magnesium	ppm	<b>4</b>			
Zinc	ppm	44			
Phosphorus	ppm	■1107			
Barium	ppm	<b>2</b>			
Boron	ppm	<b>228</b>			



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10565997Signed:Wes DavisReport Date:24 Jul 2023



## **CONSTRUCTION EQUIPMENT**





