



# CONSTRUCTION EQUIPMENT

579734 CENTRAL SITE VOLVO EC350EL 314163 - REAR LEFT FINAL DRIVE



**Sample No:** VCP412094  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 579734 CENTRAL SITE



## SAMPLE INFORMATION

Sample Number	<b>VCP412094</b>	VCP411058	---	---
Sample Date	<b>15 Jul 2023</b>	30 May 2023	---	---
Machine Hours	<b>2085</b>	1984	---	---
Oil Hours	<b>85</b>	1000	---	---
Oil Changed	<b>Changed</b>	Changed	---	---
Sample Status	<b>NORMAL</b>	ABNORMAL	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: JOHN FARDELLA  
 JFARDELLA@ALTAEQUIPFL.COM  
 T: (813)630-0077  
 F: (813)630-2233



## OIL CONDITION

Visc @ 40°C	cSt	<b>234</b>	210	---	---
-------------	-----	------------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	<b>62</b>	175	---	---
Sodium	ppm	<b>0</b>	0	---	---
Potassium	ppm	<b>1</b>	2	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	<b>332</b>	961	---	---
Copper	ppm	<b>&lt;1</b>	2	---	---
Lead	ppm	<b>&lt;1</b>	0	---	---
Tin	ppm	<b>0</b>	0	---	---
Aluminum	ppm	<b>4</b>	12	---	---
Chromium	ppm	<b>8</b>	22	---	---
Molybdenum	ppm	<b>18</b>	4	---	---
Nickel	ppm	<b>&lt;1</b>	2	---	---
Titanium	ppm	<b>&lt;1</b>	1	---	---
Silver	ppm	<b>0</b>	0	---	---
Manganese	ppm	<b>3</b>	10	---	---
Vanadium	ppm	<b>0</b>	0	---	---



## ADDITIVES

Calcium	ppm	<b>244</b>	134	---	---
Magnesium	ppm	<b>63</b>	16	---	---
Zinc	ppm	<b>178</b>	92	---	---
Phosphorus	ppm	<b>932</b>	699	---	---
Barium	ppm	<b>2</b>	0	---	---
Boron	ppm	<b>139</b>	50	---	---

**Depot:** VOLVO0093  
**Unique No:** 10566017  
**Signed:** Don Baldrige  
**Report Date:** 25 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

