

CONSTRUCTION EQUIPMENT 580298 VOLVO L220H 3368 - REAR AXLE



Sample No: VCP425445
Oil Type: VOLVO WB 102

Job No: 580298

SAMPLE	INFORMATION				
Sample Number		VCP425445	VCP369989	VCP360951	
Sample Date		18 Jul 2023	13 Oct 2022	10 May 2022	
Machine Hours		3780	2139	1160	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Not Changd	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL CON	NITION				
			- 40 F	- 40 C	
/isc @ 40°C	cSt	47.6	40.5	40.6	
VOLVO					
CONTAN	MINATION				
Silicon	ppm	12	1 0	1 1	
Sodium	ppm	4	8	■8	
Potassium	ppm	0	1 0	■3	
Otassiaiii	PPIII				
VOLVO					
WEAR N	METALS				
ron	ppm	■83	4 5	■34	
Copper	ppm	42	■8	2	
Lead	ppm	0	< 1	0	
Γin	ppm	■ 0	- <1	□0	
Aluminum	ppm	2	- < 1	1	
Chromium	ppm	2	2	2	
Molybdenum	ppm	2	2	2	
Vickel	ppm	■ 0	0	0	
Γitanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■ 3	□ 3	■ 3	
/anadium	ppm	0	0	0	
ADDITIV	IFS				
_		4052	E 20.42	E 4124	
Calcium	ppm	4052	3843	4134	
Magnesium	ppm	24	10	9	
Zinc	ppm	1679	■ 1524	□ 1754	
Phosphorus	ppm	1386	1274	■ 1438	
Barium	ppm	0	0	0	
Boron	ppm	130	131	151	

Report Id: BLUFOR [WUSCAR] 05904668 (Generated: 07/24/2023 08:51:52) Rev: 1



BLUE GOOSE GROWERS

16059 W ORANGE AVE FT PIERCE, FL US 34945 Contact: SERVICE MANAGER

T: (772)461-3020

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:BLUFORUnique No:10566024Signed:Wes DavisReport Date:24 Jul 2023



CONSTRUCTION EQUIPMENT





