

## **CONSTRUCTION EQUIPMENT**

SWA298751 VOLVO A45G 342523 - WET DISC BRAKE



Sample No: VCP419035

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

**Job No:** SWA298751

VOLVO SAMPLE	INFORMATION				
	INI ORMATION		<del>-</del>		
Sample Number		VCP419035			
Sample Date		18 Jul 2023			
Machine Hours		6542			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		ABNORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	<b>42.9</b>			
VOLVO					
CONTAM	IINATION				
Silicon	ppm	<b>1</b> 4			
Sodium	ppm	<b>■</b> 3			
Potassium	ppm	<b>2</b>			
WEAR M	IETALS				
Iron	ppm	<b>15</b>			
Copper	ppm	<u> </u>			
Lead	ppm	<b>■&lt;1</b>			
Tin	ppm	O			
Aluminum	ppm	<b>2</b>			
Chromium	ppm	<b>■&lt;1</b>			
Molybdenum	ppm	<b>1</b>			
Nickel	ppm	<b>2</b>			
Titanium	ppm	0			
Silver	ppm	<1			
Manganese	ppm	<b>■&lt;1</b>			
Vanadium	ppm	0			
	Jan. 17	_			
VOLVO	IFC .				
ADDITIV	FZ				
Calcium	ppm	<b>4237</b>			
Magnesium	ppm	<b>18</b>			
Zinc	ppm	<b>1712</b>			
Phosphorus	ppm	<b>1350</b>			
Barium	ppm	<b></b>			
Boron	ppm	<b>145</b>			



QGS - QUALITY GRASSES SERV/TCF LEASING 17502 CR 672 LITHIA, FL US 33547 Contact: GARY ROGERS grogers@qgsdevelopment.com T: (813)323-4119

## Diagnosis

F:

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:QUALITFLUnique No:10566406Signed:Sean FeltonReport Date:25 Jul 2023



## **CONSTRUCTION EQUIPMENT**





