



# CONSTRUCTION EQUIPMENT

286664 PASCO EXC VOLVO L150H 7073 - TRANSMISSION (AUTO)



**Sample No:** VCP424514  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 286664 PASCO EXC



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: JOHN FARDELLA  
 JFARDELLA@ALTAEQUIPFL.COM  
 T: (813)630-0077  
 F: (813)630-2233



## SAMPLE INFORMATION

Sample Number	VCP424514	---	---	---
Sample Date	21 Jun 2023	---	---	---
Machine Hours	2043	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 27.6	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 1	---	---	---



## WEAR METALS

Iron	ppm	█ 76	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 75	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 8	---	---	---
Phosphorus	ppm	█ 190	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 74	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO0093  
**Unique No:** 10573640  
**Signed:** Wes Davis  
**Report Date:** 26 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

