

CONSTRUCTION EQUIPMENT
567450 MOSAIC TAKEUCHI TB2150 514601123 - DIESEL ENGINE

Sample No: VCP408277

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 567450 MOSAIC

SAMPLE IN	IFORMATION			
Sample Number	<u>-</u>	VCP408277		
Sample Date		30 Jun 2023		
Machine Hours		477		
Oil Hours		80		
Oil Changed		Changed		
Sample Status		NORMAL		
OIL CONDIT	LIUN			
	IUN		- <u>-</u> -	
Visc @ 100°C	cSt	13.8		
Base Number (BN)	mg KOH/g	10.5		
Oxidation (PA)	%	73		
VOLVO	ATION			
CONTAMIN	IATIUN			
Soot %	%	■ 0.2		

CONTAMINATION						
Soot %	%	■ 0.2				
Nitration (PA)	%	74				
Sulfation (PA)	%	58				
Glycol	%	NEG				
Fuel	%	<1.0				
Silicon	ppm	15				
Sodium	ppm	4				
Potassium	ppm	2				

WEAR	METALS			
Iron	ppm	26	 	
Copper	ppm	11	 	
Lead	ppm	0	 	
Tin	ppm	■<1	 	
Aluminum	ppm	■ 3	 	
Chromium	ppm	■ 2	 	
Molybdenum	ppm	1	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	■0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	

ADDITIVES					
Calcium	ppm	2366			
Magnesium	ppm	161			
Zinc	ppm	■848			
Phosphorus	ppm	711			
Barium	ppm	6			
Boron	ppm	■33			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA JFARDELLA@ALTAEQUIPFL.COM T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 10573990 Signed: Wes Davis Report Date: 27 Jul 2023



CONSTRUCTION EQUIPMENT





