## CONSTRUCTION EQUIPMENT 567884 MOSAIC VOLVO EC380EL 314879 - DIESEL ENGINE

Sample No: VCP416009

ZOLV

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3 Job No: 567884 MOSAIC

## SAMPLE INFORMATION

Sample Number	-	VCP416009					
Sample Date		28 Jun 2023					
Machine Hours		1116					
Oil Hours		500					
Oil Changed		Changed					
Sample Status		ABNORMAL					
Visc @ 100°C	cSt	🔺 12.2					
Base Number (BN)	mg KOH/g	8.9					
Oxidation (PA)	%	80					
CONTAMIN							
CONTAMINATION							
Soot %	%	0.1					
Nitration (PA)	%	67					
Sulfation (PA)	%	61					
Glycol	%	NEG					
Fuel	%	0.4					
Silicon	ppm	8					
Sodium	ppm	3					
Potassium	ppm	0					

WEAR METAL

WEAN I	METALS			
Iron	ppm	9	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	0	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	□<1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	45	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	□<1	 	
Vanadium	ppm	<1	 	

ADDITIVES							
Calcium	ppm	<b>1888</b>					
Magnesium	ppm	<b>494</b>					
Zinc	ppm	1142					
Phosphorus	ppm	965					
Barium	ppm	0					
Boron	ppm	<b>40</b>					
		_					



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA JFARDELLA@ALTAEQUIPFL.COM T: (813)630-0077 F: (813)630-2233

## Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level is abnormal. All other component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

 Depot:
 VOL<sup>1</sup>

 Unique No:
 1057

 Signed:
 Don

 Report Date:
 27 Ju

VOLVO0093 10573996 Don Baldridge 27 Jul 2023

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

