



# CONSTRUCTION EQUIPMENT

## 23740 VOLVO L60H 1123 - REAR AXLE



**Sample No:** VCP404620  
**Oil Type:** VOLVO WB 102  
**Job No:** 23740



### SAMPLE INFORMATION

Sample Number	VCP404620	---	---	---
Sample Date	20 Jul 2023	---	---	---
Machine Hours	9337	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

218 - ASCENDUM MACHINERY INC - N. CHARLESTON  
 7235 CROSS COUNTRY RD.  
 NORTH CHARLESTON, SC  
 US 29418  
 Contact: MATT MITCHAM  
 matt.mitcham@ascendummachinery.com  
 T:  
 F: (843)414-1129



### OIL CONDITION

Visc @ 40°C	cSt	█41.1	---	---	---
-------------	-----	-------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█26	---	---	---
Sodium	ppm	█4	---	---	---
Potassium	ppm	█0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█393	---	---	---
Copper	ppm	█42	---	---	---
Lead	ppm	█14	---	---	---
Tin	ppm	█3	---	---	---
Aluminum	ppm	█2	---	---	---
Chromium	ppm	█8	---	---	---
Molybdenum	ppm	█9	---	---	---
Nickel	ppm	█1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█9	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█4197	---	---	---
Magnesium	ppm	█16	---	---	---
Zinc	ppm	█1736	---	---	---
Phosphorus	ppm	█1433	---	---	---
Barium	ppm	█0	---	---	---
Boron	ppm	█148	---	---	---

**Depot:** VOLVO3387  
**Unique No:** 10574605  
**Signed:** Wes Davis  
**Report Date:** 27 Jul 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

