CONSTRUCTION EQUIPMENT SWA296880 KUBOTA SVL75 KBCZ052CPM1B65747 - DIESEL FL

Sample No: VCP423153 **Oil Type:** NOT GIVEN Job No: SWA296880

VOLVO

SAMPLE	INFORMATIO	N		
Sample Number		VCP423153	 	
Sample Date		21 Jul 2023	 	
Machine Hours		506	 	
Sample Status		NORMAL	 	
FUEL CO	NDITION			
Sulfur	ppm	0	 	
Visc @ 40°C	cSt	3.07	 	
CONTAM	INATION			
Water	%	0.003	 	
Lead	ppm	 <1	 	
Nickel	ppm	0	 	
Aluminum	ppm	0	 	
Vanadium	ppm	0	 	
Silicon	ppm	0	 	



ALTA EQUIPMENT CO - ORLAND PARK

5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time.All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot: VOLVO8885 Unique No: 10574741 Signed: Jonathan Hester Report Date: 31 Jul 2023



VOLVO

GRAPHS



Pensky-Martens Flash Point (°C)

	_			-	empe	statute	د				
	10	-8	-6	-4	-2	0	2	4	6	8	10.
000 000 1		ļ	Į,		Į.	ļ.	Į.	1	ļ,	ļ.	-
Julz 1/23	Ļ			i			i.	i		İ.	
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
	_										
											_
											_
0010111	_										
Julz 1/23	Ļ		Ì	1			i.	1		1	