



CONSTRUCTION EQUIPMENT

VOLVO L180H 5715 - COOLANT



Sample No: VCP0004653
Oil Type: HYBRID (HOAT) COOLANT
Job No:



SAMPLE INFORMATION

Sample Number	VCP0004653	---	---	---
Sample Date	21 Jul 2023	---	---	---
Machine Hours	670	---	---	---
Sample Status	NORMAL	---	---	---

DUNN CONSTRUCTION INC
 318 N 14TH ST
 BELLEVUE, IA
 US 52031
 Contact: STEVE DUNN
 DUNNCONSTRUCTINC@GMAIL.COM
 T:
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.71	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 44.0	---	---	---
Freezing Point	°C	■ -21	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: DUNBEL
Unique No: 10574756
Signed: Doug Bogart
Report Date: 30 Jul 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

