CONSTRUCTION EQUIPMENT SW0-063977 CATERPILLAR 769C 01X06337 - FRONT RIGHTEINAL

 Sample No:
 VCP369087

 Oil Type:
 NOT GIVEN

 Job No:
 SWO-063977

Vanadium

ppm

VOLVO

SAMPLE INFORMATION VCP369087 Sample Number Sample Date 24 Jul 2023 Machine Hours 3379 Oil Hours 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 58.5 CONTAMINATION Silicon ppm 19 Sodium 2 ppm Potassium 0 🔲 ppm WEAR METALS Iron ppm 106 Copper ppm **4** Lead ppm 0 🔲 0 Tin ppm Aluminum ppm 2 Chromium ppm ■ <1 Molybdenum 2 ppm Nickel ppm <1 Titanium <1 ppm Silver 0 ppm Manganese 1 ppm

ADDITIVES 1347 Calcium ppm Magnesium 18 ppm 778 Zinc ppm 661 Phosphorus ppm Barium 0 ppm Boron ppm 5

0



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905 F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:WHIGUNUnique No:10575842Signed:Don BaldridgeReport Date:30 Jul 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: WHIGUN [WUSCAR] 05909190 (Generated: 07/30/2023 11:39:43) Rev: 1

Contact/Location: BROTHER WHITAKER - WHIGUN