Sample No: VCP419154

Oil Type: VOLVO AT 102

Job No: SWA253761

VOLVO	INCODMATION	J		
	INFORMATION			
Sample Number		VCP419154	VCP408830	
Sample Date		21 Jul 2023	26 Apr 2023	
Machine Hours		49379	48761	
Oil Hours		0	0	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	SEVERE	
OIL CON	DITION			
Visc @ 40°C	cSt	■32.0	□ 26.7	
VOLVO				
CONTAN	IINATION			
Silicon	ppm	4	4	
Sodium	ppm	14	0	
Potassium	ppm	14	2	
WEAR M	IETAL C			
_	IC I AC2	·		
Iron	ppm	147	379	
Copper	ppm	4	7	
Lead	ppm	■0	0	
Tin	ppm	■ 0	0	
Aluminum	ppm	1	□0	
Chromium	ppm	■<1	0	
Molybdenum	ppm	0	- <1	
Nickel	ppm	0	0	
Titanium	ppm	0	0	
Silver	ppm	■0	0	
Manganese	ppm	2	3	
Vanadium	ppm	0	0	
ADDITIV	ES			
Calcium	ppm	■99	□90	
Magnesium	ppm	18	<1	
Zinc	ppm	214	17	
Phosphorus	ppm	222	167	
Barium	ppm	■0	0	
Boron	ppm	60	6 4	
	1.1.		_	



WHEELABRATOR

1 CHARLES POINT AVE PEEKSKILL, NY US 10566

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:WHEPEEUnique No:10577025Signed:Don BaldridgeReport Date:31 Jul 2023



CONSTRUCTION EQUIPMENT





