

CONSTRUCTION EQUIPMENT VOLVO L260H VCP 361797 (S/N NOT GIVEN) - COOLANT



Sample No: VCP361797

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No:

SAMPLE II	NFORMATION				
Sample Number	-	VCP361797			
Sample Date		26 May 2023			
Machine Hours		1498			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.26			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	0			
Percentage Glycol	%	46.2			
Freezing Point	°C	-26			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Yllow			

SARGENT DOCKS

5606 N WESTERVELT RD SAGINAW, MI US 48604 Contact: JC NUDDE JCNUDDE@SARGENTDOCKS.COM T: (989)752-3101 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SARSAGUnique No:10577329Signed:Doug BogartReport Date:31 Jul 2023

Contact/Location: JC NUDDE - SARSAG



CONSTRUCTION EQUIPMENT





GRAPHS

