CONSTRUCTION EQUIPMENT x58329 TADANO GR350XL NOT GIVEN VCP413466 - DIESEL ENGL

Sample No:	VCP413466
Oil Type:	NOT GIVEN
Job No:	X58329

VOLVO

VOLVO				
SAMPLE IN	FORMATION			
Sample Number		VCP413466		
Sample Date		24 Jul 2023		
Machine Hours		584		
Oil Hours		0		
Oil Changed		N/A		
Sample Status		NORMAL		
OIL CONDI	TION			
Visc @ 100°C	cSt	13.2		
Base Number (BN)		10.7		
Oxidation (PA)	%	78		
<u> </u>	-	_	<u>.</u>	 <u> </u>
Soot %	%	0.1		
Nitration (PA)	%	43		
Sulfation (PA)	%	59		
Glycol	%	NEG		
Fuel	%	<1.0		
Silicon	ppm	11		
Sodium	ppm	3		
Potassium	ppm	3		

WFAR METALS

WLAK I	METALS			
Iron	ppm	12	 	
Copper	ppm	7	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	3	 	
Chromium	ppm	 <1	 	
Molybdenum	ppm	48	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	maa	<1	 	

ADDITIVES						
ppm	1795					
ppm	436					
ppm	1124					
ppm	919					
ppm	0					
ppm	84					
	ppm ppm ppm ppm	ppm 436 ppm 1124 ppm 919 ppm 0	ppm 436 ppm 1124 ppm 919 ppm 0	ppm 436 ppm 1124 ppm 919 ppm 0		



SCOTT EQUIPMENT COMPANY LLC - Saint Rose

PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961 F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.


Depot:SCOSAIUnique No:10577365Signed:Don BaldridgeReport Date:01 Aug 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SCOSAI [WUSCAR] 05910713 (Generated: 08/01/2023 10:09:13) Rev: 1

Contact/Location: DENISE CORVERS - SCOSAI