CONSTRUCTION EQUIPMENT 301300-20 JHS BUILD TAKEUCHI TB235 123600202 - FRONT RIG

Sample No: VCP420606 **Oil Type:** NOT GIVEN Job No: 301300-20 JHS BUILD

VOLVO

				- 3
	E INFORMATION	N		
Sample Number		VCP420606	 	 
Sample Date		25 Jul 2023	 	 ALT
Machine Hours		2419	 	 515
Oil Hours		0	 	 FOR
Oil Changed		Changed	 	 US
Sample Status		SEVERE	 	 Con
				tlark
OIL CON				T:
Visc @ 40°C	cSt	1315	 -	F: (2
VISC @ 40 C	CSL	1315	 	
VOLVO				Dia
CONTAI	MINATION			We
Water	%	<b>0.301</b>	 	 wh
Silicon	ppm	2451	 	 oil
Sodium	ppm	3	 	 ha
Potassium	ppm	8	 	 ins
				rec
VOLVO				mo
WEAR I	METALS			the oil
Iron	ppm	• 10000	 	 inc
Copper	ppm	■43	 	 cor
Lead	ppm	<b>□</b> <1	 	 oil.
Tin	ppm	2	 	 alu
Aluminum	ppm	<b>1</b> 07	 	 silie
Chromium	ppm	🛑 116	 	 no
Molybdenum	ppm	13	 	 pre
Nickel	ppm	9 35	 	
Titanium	ppm	8	 	
Silver	ppm	0	 	
Manganese	ppm	85	 	
Vanadium	ppm	1	 	
ADDITI			 	
	-			
Calcium	ppm	716	 	

Calcium	ppm	716	 	
Magnesium	ppm	37	 	
Zinc	ppm	83	 	
Phosphorus	ppm	791	 	
Barium	ppm	0	 	
Boron	ppm	128	 	



## QUIPMENT COMPANY

MARTIN LUTHER KING BLVD YERS, FL 05 TODD LARK Itaequipfl.com 481-3302

## osis

vise that you check all areas dirt can enter the system. The nge at the time of sampling en noted. We advise that you for the source(s) of wear. We nend an early resample to r this condition. Please specify nd, type, and viscosity of the our next sample.Gear wear is ed. There is a light tration of water present in the mental levels of silicon (Si) and um (Al) indicate alumina-(coarse dirt) ingress. The oil is er serviceable due to the e of contaminants.

Depot: VOLVO0090 Unique No: 10578261 Signed: Don Baldridge Report Date: 01 Aug 2023


Contact/Location: TODD LARK - VOLVO0090

## **CONSTRUCTION EQUIPMENT**





VOLVO



Report Id: VOLVO0090 [WUSCAR] 05911609 (Generated: 08/01/2023 15:58:05) Rev: 1

Contact/Location: TODD LARK - VOLVO0090