



CONSTRUCTION EQUIPMENT

VOLVO A45G 353251 - TRANSMISSION (AUTO)



Sample No: VCP421344
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



SAMPLE INFORMATION

Sample Number	VCP421344	---	---	---
Sample Date	20 Jul 2023	---	---	---
Machine Hours	2242	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	ABNORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



OIL CONDITION

Visc @ 40°C	cSt	█ 28.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 1	---	---	---



WEAR METALS

Iron	ppm	█ 18	---	---	---
Copper	ppm	█ 10	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 1	---	---	---
Aluminum	ppm	█ 11	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 74	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 202	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 113	---	---	---

Diagnosis

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0090
Unique No: 10578272
Signed: Sean Felton
Report Date: 01 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

