



# CONSTRUCTION EQUIPMENT

309970 VOLVO A40G 352506 - COOLANT



**Sample No:** VCP420579  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 309970



## SAMPLE INFORMATION

Sample Number	VCP420579	---	---	---
Sample Date	22 Jul 2023	---	---	---
Machine Hours	5710	---	---	---
Sample Status	NORMAL	---	---	---



## COOLANT CONDITION

pH	Scale 0-14	■ 7.20	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.0	---	---	---
Freezing Point	°C	■ -33	---	---	---



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yellow	---	---	---

### SOUTH FLORIDA EXCAVATION

1455 RAIL HEAD BLVD STE 3  
NAPLES, FL  
US 34110-8407

Contact: ROB ANDERSON  
CHOEHI@EMBARQMAIL.COM;XJ\_GERRARD@YAHOO.COM;ROBDIGSDIRT@AOL.COM  
T: (239)596-8111  
F: (239)596-8112

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** SOUNAPFL  
**Unique No:** 10578388  
**Signed:** Jonathan Hester  
**Report Date:** 02 Aug 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

