



CONSTRUCTION EQUIPMENT

9385 VOLVO L70H 624024 - FRONT AXLE



Sample No: VCP423120
Oil Type: VOLVO WB 102
Job No: 9385



SAMPLE INFORMATION

Sample Number	VCP423120	---	---	---
Sample Date	27 Jul 2023	---	---	---
Machine Hours	1048	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

RELIABLE CONTRACTING
 2410 EVERGREEN RD SUITE 200
 GAMBRILLS, MD
 US 21054
 Contact: RUSSELL HATFIELD
 RHATFIELD@RELIABLECONTRACTING.COM
 T: (410)987-1851
 F:



OIL CONDITION

Visc @ 40°C	cSt	■ 39.6	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 11	---	---	---
Sodium	ppm	■ 10	---	---	---
Potassium	ppm	■ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	■ 44	---	---	---
Copper	ppm	■ <1	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ 2	---	---	---
Molybdenum	ppm	■ 10	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 8	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	■ 3789	---	---	---
Magnesium	ppm	■ 13	---	---	---
Zinc	ppm	■ 1573	---	---	---
Phosphorus	ppm	■ 1272	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 132	---	---	---

Depot: RELMIL
Unique No: 10586778
Signed: Wes Davis
Report Date: 04 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

