



# CONSTRUCTION EQUIPMENT

## SPM580911 VOLVO EC250ELR 314201 - SWING DRIVE



**Sample No:** VCP423129  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM580911



### SAMPLE INFORMATION

Sample Number	<b>VCP423129</b>	VCP346074	---	---
Sample Date	<b>21 Jul 2023</b>	02 Apr 2022	---	---
Machine Hours	<b>2533</b>	527	---	---
Oil Hours	<b>0</b>	0	---	---
Oil Changed	<b>Not Chngd</b>	Not Chngd	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

**BELSON STEEL**  
 1685 N STATE RTE 50  
 BOURBONNAIS, IL  
 US 60914  
 Contact: M. POZAN  
 mpozan@belsonsteel.com  
 T: (815)932-7416  
 F:



### OIL CONDITION

Visc @ 40°C	cSt	<b>149</b>	163	---	---
-------------	-----	------------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	<b>14</b>	6	---	---
Sodium	ppm	<b>2</b>	1	---	---
Potassium	ppm	<b>2</b>	0	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	<b>304</b>	203	---	---
Copper	ppm	<b>10</b>	14	---	---
Lead	ppm	<b>&lt;1</b>	0	---	---
Tin	ppm	<b>0</b>	0	---	---
Aluminum	ppm	<b>2</b>	1	---	---
Chromium	ppm	<b>3</b>	2	---	---
Molybdenum	ppm	<b>1</b>	1	---	---
Nickel	ppm	<b>0</b>	0	---	---
Titanium	ppm	<b>&lt;1</b>	0	---	---
Silver	ppm	<b>0</b>	<1	---	---
Manganese	ppm	<b>4</b>	4	---	---
Vanadium	ppm	<b>&lt;1</b>	0	---	---



### ADDITIVES

Calcium	ppm	<b>20</b>	16	---	---
Magnesium	ppm	<b>6</b>	0	---	---
Zinc	ppm	<b>18</b>	14	---	---
Phosphorus	ppm	<b>505</b>	314	---	---
Barium	ppm	<b>0</b>	0	---	---
Boron	ppm	<b>8</b>	<1	---	---

**Depot:** BELBOU  
**Unique No:** 10586800  
**Signed:** Wes Davis  
**Report Date:** 04 Aug 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

