



CONSTRUCTION EQUIPMENT

2901 VOLVO A40G 352199 - REAR AXLE



Sample No: VCP404648
Oil Type: MOBIL MOBILUBE HD PLUS 80W90
Job No: 2901



SAMPLE INFORMATION

Sample Number	VCP404648	VCP385106	VCP385419	VCP366912
Sample Date	19 Jul 2023	13 Feb 2023	01 Nov 2022	22 Aug 2022
Machine Hours	5644	4597	4083	3567
Oil Hours	1047	1030	516	993
Oil Changed	Changed	Changed	Not Changd	Changed
Sample Status	NORMAL	ABNORMAL	NORMAL	ATTENTION

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	131	125	125	▲ 49.5
-------------	-----	------------	-----	-----	--------



CONTAMINATION

Silicon	ppm	6	5	6	4
Sodium	ppm	<1	<1	1	1
Potassium	ppm	<1	0	0	2



WEAR METALS

Iron	ppm	25	198	142	144
Copper	ppm	<1	<1	4	2
Lead	ppm	0	0	0	0
Tin	ppm	0	0	0	0
Aluminum	ppm	0	1	1	<1
Chromium	ppm	<1	3	2	2
Molybdenum	ppm	<1	2	3	4
Nickel	ppm	0	0	0	0
Titanium	ppm	<1	<1	0	0
Silver	ppm	0	0	0	<1
Manganese	ppm	<1	4	4	5
Vanadium	ppm	<1	0	0	0



ADDITIVES

Calcium	ppm	401	452	512	74
Magnesium	ppm	9	12	4	<1
Zinc	ppm	139	162	179	33
Phosphorus	ppm	949	932	1029	2293
Barium	ppm	0	0	0	0
Boron	ppm	175	171	165	278

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SCHGRE
Unique No: 10586817
Signed: Wes Davis
Report Date: 04 Aug 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

