

## **CONSTRUCTION EQUIPMENT**

VOLVO L120F 66421 - HYDRAULIC SYSTEM



Oil Type: **VOLVO SUPER HYDRAULIC OIL 46** 

Job No: 19161 GFI





117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST GREENVILLE, NC

US 27834

Contact: BRANDON JENKINS BRANDON.JENKINS@ASCENDUMMACHINERY.COM

F: (704)494-8197

## Diagnosis

We advise that you check for the source of water entry. We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. Appearance is milky. There is a moderate amount of particulates present in the oil. There is a moderate concentration of water present in the oil. The AN level is acceptable for this fluid.

VOLVO8769 Depot: **Unique No:** 10587197 Signed: Jonathan Hester **Report Date:** 09 Aug 2023

ppm

ppm

ppm

Phosphorus

Barium

Boron

**332** 

**0** 

**0** 



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

