



CONSTRUCTION EQUIPMENT

SWO-064541 VOLVO A60H 350051 - REAR RIGHT FINAL DRIVE



Sample No: VCP369317
Oil Type: GEAR OIL SAE 80W90
Job No: SWO-064541



SAMPLE INFORMATION

Sample Number	VCP369317	VCP424538	VCP380965	VCP364263
Sample Date	03 Aug 2023	28 Apr 2023	21 Dec 2022	31 Aug 2022
Machine Hours	6858	6390	5828	5303
Oil Hours	0	0	0	0
Oil Changed	Not Chngd	Not Chngd	Changed	Not Chngd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD
 BIRMINGHAM, AL
 US 35207

Contact: STEPHANI BRITTON
 sbritton@saiia.com;doug.bogart@wearcheck.com
 T: (205)943-2268
 F: (205)943-2269



OIL CONDITION

Visc @ 40°C	cSt	278	278	139	139
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	3	4	1	1
Sodium	ppm	0	<1	<1	0
Potassium	ppm	2	<1	<1	0



WEAR METALS

Iron	ppm	53	67	21	13
Copper	ppm	<1	<1	<1	<1
Lead	ppm	0	0	0	<1
Tin	ppm	0	0	0	0
Aluminum	ppm	0	<1	0	0
Chromium	ppm	1	2	<1	<1
Molybdenum	ppm	3	3	3	3
Nickel	ppm	<1	<1	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	<1	0	0	0
Manganese	ppm	2	2	<1	1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	69	67	57	44
Magnesium	ppm	14	17	25	18
Zinc	ppm	48	53	85	76
Phosphorus	ppm	1024	1079	1012	888
Barium	ppm	0	0	0	0
Boron	ppm	193	174	52	58

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SAIBIR
Unique No: 10589846
Signed: Sean Felton
Report Date: 08 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

