



# CONSTRUCTION EQUIPMENT

580677 APTIM VOLVO A35G 340041 - COOLANT



**Sample No:** VCP417003  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 580677 APTIM



## SAMPLE INFORMATION

Sample Number	VCP417003	---	---	---
Sample Date	28 Jul 2023	---	---	---
Machine Hours	12724	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## COOLANT CONDITION

pH	Scale 0-14	■ 7.56	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.5	---	---	---
Freezing Point	°C	■ -33	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO0093  
**Unique No:** 10589916  
**Signed:** Jonathan Hester  
**Report Date:** 09 Aug 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

