



CONSTRUCTION EQUIPMENT

A10714 VOLVO EC160E 314283 - REAR LEFT FINAL DRIVE



Sample No: VCP411930
Oil Type: MOBIL MOBILUBE HD 80W90
Job No: A10714



HOFFMAN EQUIPMENT - LIONVILLE
 120 GORDON DRIVE
 LIONVILLE, PA
 US 19341
 Contact: JIM FEHR
 jim.fehr@hoffmanequip.com
 T: (610)363-9200
 F: (610)594-0829



SAMPLE INFORMATION

Sample Number	VCP411930	---	---	---
Sample Date	25 Jul 2023	---	---	---
Machine Hours	425	---	---	---
Oil Hours	425	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 183	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 78	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 8	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 4	---	---	---
Phosphorus	ppm	█ 259	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8879
Unique No: 10601776
Signed: Don Baldrige
Report Date: 12 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

